

Premier Series Self Contained Hot Water Washer





The Premier Series provides the highest level of quality & performance available in the industry today.



The Premier Series is compatible with all Streamliner trailers.



COIL SYSTEM

Our exclusive "Cool Touch Coil" actually forms the combustion chamber, eliminating troublesome insulation and outside hot spots. It also allows for better air flow which in turn provides better fuel combustion and efficiency.



ACCUMULATOR ASSEMBLY The All American Accumulator Assembly effectively manages high-pressure flow conditions that may ordinarily cause system failure.



UNLOADER ASSEMBLY Heavy-duty mounting of easy access pressure regulating valve eliminates fitting fatigue failure found in other manufacturers.



PUMP ASSEMBLY Heavy-duty triplex plunger pump for years of dependable use.

MODEL #	GPM	PSI	HP	ENGINE	VOLT	BURNER
PH5030VBOF	5.0	3000	16	VANGUARD	12 VDC	OIL FIRED
PH5030VGOD	5.0	3000	18	VANGUARD	115 V	OIL FIRED
PH5030KGOD	5.0	3000	18	KOHLER	115 V	OIL FIRED
PH5035KBOF	5.0	3500	18	KOHLER	12 VDC	OIL FIRED
PH5035HGOD	5.0	3500	20	HONDA	115 V	OIL FIRED
PH5035HBOF	5.0	3500	20	HONDA	12VDC	OIL FIRED
PH8030HGOD	8.0	3000	24	HONDA	115 V	OIL FIRED
PH5030DGOD	4.5	3000	14	KUBOTA (DIESEL)	115 V	OIL FIRED
PH5035KGPD	5.0	3500	18	KOHLER	PILOT LIGHT	PROPANE

5-1 YEAR LIMITED WARRANTY

- 5 years on pump & Cool Touch Coil
- 2 years on gasoline engines
- 1 year on remaining components

FEATURES

- 12 volt or 115 volt oil fired burners
- 1" tubular steel frame construction
- Stainless steel panels
- Adjustable temperature control
- Adjustable upstream detergent injection
- Dual 18 gallon fuel tanks
- Four quick-change spray nozzles
- Inlet float tank
- Belt-driven triplex plunger pump
- 2000 watt generator (115 V only)
- Electric start gasoline engine
- Shut-off gun
- 36" wand
- 50' high pressure hose
- Stainless steel corrosion free coil wrap



105 Broad Street, P0 Box 288 Alcester, South Dakota, USA 57001 TEL: 800-541-7267 • FAX: 800-325-5682

www.allamericancleaningsystems.com



Bulletin #185